



New Product Announcement – Spicer® Double Cardan CV Ball Seat Repair Kits

Date: **May 28, 2019**

To: **All Dana Aftermarket Group Spicer Driveshaft Customers**

Dana Aftermarket Group is pleased to announce the release of our new Spicer® Double Cardan CV Ball Seat Repair Kits. From passenger cars and commercial trucks, to off-highway equipment and industrial applications, technicians trust genuine Spicer universal joints to get the job done right, the first time!

Each Spicer Double Cardan CV Ball Seat Repair Kit contains the ball socket with retainer, spring, and 2 seals. Offered in both greaseable and non-greaseable versions.

Part #	UPC	Greaseable/Non-Greaseable	Competitive Interchange Numbers	
10018440	023913797690	Non-Greaseable	7-0081NG	617
10018465	023913797706	Greaseable	7-0081	612

Please contact your Dana Aftermarket Group sales representative for more details, or visit our E-Catalog at DanaAftermarket.com.

Thank you for your continued support of Spicer aftermarket products.

Steve Jansing

Product Manager

Spicer Driveline Products

SpicerParts.com/Performance

Dana Aftermarket Group

PO Box 1000 Maumee, Ohio 43537

Warehouse Distributors: 1.800.621.8084

OE Dealers: 1.877.777.5360

Follow SpicerParts [f](#) [t](#) [@](#) [v](#) [in](#)